



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 710**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 710

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 710. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 711**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 711

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 711. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 712**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 712

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 712. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 713**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 713

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 713. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 714**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 714

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 714. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 715**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 715

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 715. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 716**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 716

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 716. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 717**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 717

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 717. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 718**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 718

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 718. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 719**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 719

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 719. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 720**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 720

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 720. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager



47 National Avenue,
Pakenham VIC 3810

ph: 03 9769 5799
fax: 03 9769 4799
mob: 0417 004 072
tseymour@terrafirmalabs.com.au

www.terrafirmalabs.com.au

ABN: 11 925 206 385

**Geotechnical Report
Level One Inspection and Testing**

**Acacia Ridge Stage 5 and 7
Lot 721**

Prepared for:

The Land Owner

PROJECT No 9384

03 May 2017.

Prepared by:

TERRA FIRMA LABORATORIES
Geotechnical Inspection and Testing Authority

47 National Avenue,
Pakenham VIC 3810
Phone: 03 9769 5799 Fax: 03 9769 4799
Email: tseymour@terrafirmalabs.com.au

Geotechnical Report Level One Inspection and Testing Acacia Ridge Stage 5 and 7 Lot 721

1. Introduction

Terra Firma Laboratories was engaged by Streetworks Pty Ltd as the geotechnical inspection and testing authority to provide Level 1 supervision and testing works on the earthworks component for Acacia Ridge Stage 5 and 7, Lot 721. This work was conducted over the period of 18/01/2017 to 15/03/2017.

This report presents that the allotment earthworks was carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development* and in compliance with the compaction control specifications established by the contractor.

2. Scope of Works

2.1. Areas of work

The areas of work included lots 508, 509, 510, 511, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 532, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 558, 559, 560, 561, 562, 563, 564, 565, 566, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720 and 721.

Please note lot numbers 562 through to 566 contain less than 300mm of fill and as per AS3798-2007 do not require fill placement supervision and/or compaction testing. The site will be a residential estate.

The area on which fill was placed is shown on site plan (Appendix 1 as per the level one report for the entire stage) based on drawings prepared by GPR Consulting and provided by Streetworks Pty Ltd.

The supervision work by *Terra Firma Laboratories* involved both inspection of sub grade preparation work and full time inspection and testing of fill placement.

2.2. Specification

The placement of fill on the areas of work was to be carried out in accordance with *AS3798-2007 Guidelines for Earthworks for Commercial and Residential Development*, as directed by *Streetworks*. At all times during placement of fill materials Terra Firma Laboratories maintained a Geotechnical Technician on site to perform the supervision and testing as required by AS3798-2007.

As referenced from AS3798-2007 (Section 5.2) establishes a specification requirement for a minimum density ratio of not less than 95% noting that soils containing more than 20% of particles coarser than 37.5mm cannot be tested for relative compaction using the procedures of AS1289.

Field density testing shall be undertaken at a frequency of not less than 3 tests per visit.

Test Rolling is required for all layers of structural fill and materials within 150mm of permanent subgrade level so as to withstand test rolling without visible deformation or springing. Corrective action is required where unstable areas exceed 20% of the area being considered by test rolling.

3. Inspection and Testing

3.1. Sub-Grade Preparation

Subgrade preparation involved stripping the site down of topsoil and organic matter to a depth of approximately 200mm below existing levels detailed on the site plans. The sub-grade area was then proof-rolled to determine soft or otherwise unsuitable zones and such zones rectified as necessary. The sub-grade was watered and scarified prior to fill placement to aid layer bonding.

3.2. Fill materials

The materials used as fill were locally sourced and observed to generally consist of Silty Clay, sourced from stockpiled materials on site. No particles greater than 150mm were observed. The fill was nominated as clean fill by the contractor.

3.3. Fill Construction

The contractor had the following plant available on-site during the construction period for use in the fill placement:

- *Excavator*
- *Compactor*
- *Dump Truck*
- *Water Cart*
- *Scraper*
- *Pad Foot Roller*
- *Dozer*
- *Tractor*

All fill was placed in layers of thicknesses not exceeding 300mm. *The work area was typically a 2 or 3 lot area on any one particular day.* At the completion of a placed layer, compaction testing was performed to confirm appropriate compaction had been achieved and supported the observations made.

It was observed that finished levels were in accordance with levels marked on site by survey. These levels are shown on site plans attached in Appendix 1 as per the level one report for the entire stage.

The final 300mm of fill placed across the site was placed as a topsoil layer/ growing medium and should be considered as non-structural, as it was placed in an uncontrolled manner, as allowed by specifications.

4. Compaction Control Testing

Testing comprised of a total of 70 in-situ density tests, with a summary of results included in Appendix 2 as per the level one report for the entire stage. Test Reports are referenced in Appendix 3 as per the level one report for the entire stage.

Test numbers 6, 10, 15, 16, 25, 29, 31, 45, 46, 47, 53 and 55 originally failed to meet specification. *Streetworks Pty Ltd* were notified and asked to rework the area appropriately. Upon adequate reworking *Terra Firma Laboratories* would perform a re-test.; this process would continue until a minimum compaction effort of 95% was achieved.

It should be noted that the tests are a representation of the fill placed and support the visual assessment of the works completed. Each lot does not necessarily require a compaction test to comply. The compaction control testing indicated that the engineered fill on all lots complied with the technical specification.

4. Uncontrolled Works

Terra Firma Laboratories cannot verify any works completed by others after the final date specified in the introduction. Uncontrolled works may include, but not limited to trenching for services, cut and fill works for slab preparation or subsequent removal of vegetation and back fill of holes.

5. Clean Fill

Terra Firma Laboratories cannot guarantee that the material used as a filling medium is free from chemical or other contamination.

6. Statement of Compliance

Inspections and testing of the fill areas at this site indicate that both sub grade preparation and fill placement have been conducted in accordance with the specification and that the completed fill areas of greater than 300mm, as shown on the site plan attached, and not any preceding the 18/01/2017 or work completed after the 15/03/2017, may be certified as being compliant with the specification.

For and on behalf of
Terra Firma Laboratories,



Tom Seymour
Lab Manager