

P.O., BOX 7760. GAPBUTT B.C., Q., 4814. PHONE (07) 4774 7886. FAX (07) 4774 7677 med I in Expression

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 276 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760 GARBUT B.C. Q. 4814, PHONE [07] 4774 7886 FAX [07] 4774 7617

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 277 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



PIOL BOX 7760, GARBUT B.C. Q. 4814. PHONE: (D7) 4774 7886, FAX: (D7) 4774 7677 secil @bigpond.com

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 354 - Eden's Crossing Stage 4A

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger Soil Engineering Services



ниц сове РРГ 10 ACA 1066-469 769 ABN 34 149 087 182 AFF WILL FAMAY TRIST TA.

P.O. BOX 7760, GARBUTT B.C. Q. 4814. PHONE: (07) 4774 7888, FAX: (07) 4774 7677
ses01@bigpond.com

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 355 - Eden's Crossing Stage 4A

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger Soil Engineering Services



P/O, BOX 7760, GARBUTE B.C. Q. 4814, PHONE: (0.7) 4774 7888, FAX (0.7) 4774 7677 seed to bippond.com

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 371 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760 GARBUTT B.C. Q. 4814. PHONE [07] 4774 7886. FAX [07] 4774 7617 and Library of Corn

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 372 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760, GARBUTT BLC, Q. 4614, PHONE :07] 4774 7886, FAX :07; 4774 7677 heads cooperation

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 396 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 776Q. GARBUTT B.C. Q. 4814. PHONE: [07] 4774 7888, FAX: [07] 4774 7677. and I disapport core.

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 390 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



BOLBOX 7760. GARBUTTILC, Q. 4814. PHONE (07) 4774 7866. FAX (07) 4774 7677 intel full providence.

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 391 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



POLICO 7760 CARRITI N.C. Q. ABIA. PHORE [07] 4774 7886 FAX [07] 4774 7677 mm/limits of contract of the contrac

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 392 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.C. BOX 7760 G-7897 B.C. Q. 4814, PHONE :07; 4774 7886, FAX (07; 4774 7617 BBC) Q. 4814 PBC | 107; 4774 7617

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 393 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



POLBOX 7760 CARBUTT R.C. Q. 4814, PHONE (07) 4774 7888, FAX (07) 4774 7617 and Epop of zon

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 394 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760 GAPRUT B.C. Q. 4614, Provide 07; 4774 7866, FAX (07) 4774 7617 head to opposite on

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 395 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760, GARBUT B.C. Q. 4614, PHONE (07) 4774 7886, FAX (07) 4774 7677 med 1 @ringports.com

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 397 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P/O, BOX 7760 GARBUT BLC; Q, 4814, PHONE: 07] 4774 7886, FAX: J07] 4774 7617 self-fill (G) 2014 100 CARBUT BLC; Q, 4814, PHONE: 07] 4774 7886, FAX: J07] 4774 7617

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 398 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



70, 80X 7760, GARBUTT B.C. Q. 4814, PHONE [07] 4774 7886, FAX [07] 477X 7617 and a both discrete

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 399 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



PO, BOK 7760, GARBUTT B.C. G. 4814, PHONE (07) 4774 7866, FAX (07) 4774 7617 hard librioporal.com

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 400 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOK 7760, GARBUT R.C. Q. 4614, PHONE (D7) 4774 7886, FAX (D7) 4774 7672 hed to bopp od zoro

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 401 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



POLEON 7760, CARRILL &C. Q. 4814. PHONE (07) 4774 7886. FAX: (07) 4774 7617. head failed polycomic conti

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 402 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760 GARBUTT B.C. Q. 4814. PICUS: (07) 4774 7886, FAX (07) 4774 7617 seedthal appointment.

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 403 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760 GARBUTT B.C. Q. 4614, PHONE: 107; 4774 7886, FAX (07) 4774 7617 seed to bigporducion

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 404 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P/G, BOX 7760, GARRUTT R.C. Q. 461A, PHONE [07] 4774 7888, FAX [07] 4774 7617 smg() is dependent

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 405 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760, GARBUTT B.C. Q. 4814, PHONE (07) 4774 7886, FAX (07) 4774 2677 medi (abappontizam

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 412 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O., BOX 7760, GARBUTT B.C. Q. 4814, PHONE (02) 4774 7889, FAX (07) 4774 7677 sw016/bigpond.com

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 412 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760. GARBUTT B.C. Q. 4814. PHONE (07) 4774 7866, FAX (07) 4774 7617 and to opportunity

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 413 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



POLEOX 7760 GARBUTECO, Q. 4814, PHONE (07) 4774 7886, FAX (07) 4774 7670 seed tubic providence.

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 414 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. 60X 7760 GARBUTT &C. Q. 4814. PKONE [07] 4774 7866, FAX [07] 4774 7672 seed to be produced to be produced

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 415 – Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760. GAPHITI BLC, QL 4614. PHONE: (07) 4774 7886. FAX: (07) 4774 7677 Head Gaphiti Blc, QL 4614. PHONE: (07) 4774 7886. FAX: (07) 4774 7677

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 416 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760 GARBUT B.C. Q. 4614, PHONE (07) 4774 7866, FAX (07) 4774 7617, seed (disappredizion)

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 417 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



Fig. 80X 7760 CARRITI BLC, Q. 4614, PHONE [07] 4774 7888, FAX [07] 4774 7677 health group of the control of the

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 418 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



NO. COX 7740 GARBUT K.C. O. 4814. PICKIE (CT) 5774 7885. FAX (CT) 4774 7411

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 419 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger



P.O. BOX 7760. GARBUTT N.C. Q. 4614. PHCNE: [07; 4774 7886, FAX [07; 4774 7617 med) (arbipped from

17/09/2015

Shadforth Civil Contractors 99 Sandalwood Lane Forest Glen QLD 4556

Attention: Mr. Michael Bishop

RE: Lot 422 - Eden's Crossing Stage 5

Dear Sir,

Soil Engineering Services hereby certify that fill placement for the above allotment was carried out in accordance with AS3798 "Guidelines on Earthworks for Commercial and Residential Developments" for Level 1 supervision

Field Density Tests were carried out during the course of fill placement (testing carried out by SES Brisbane Laboratory accreditation 19460) and the works, so far as it has been able to determine, comply with the requirements

This certification does not include road works and backfill to service trenches.

Regards,

Matthew Rheinberger