

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F_Lot 2031

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2031 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2032

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2032 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2033

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2033 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2049

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2049 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2050

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2050 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2051

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2051 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2073

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2073 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2074

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2074 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2075

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2075 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2076

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2076 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2077

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2077 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2078

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2078 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2079

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2079 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2080

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2080 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2081

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2081 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2082

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2082 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2083

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2083 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2084

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2084 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2085

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2085 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2086

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2086 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2087

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2087 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2088

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2088 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2089

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2089 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2090

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2090 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2091

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2091 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2092

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2092 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2093

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2093 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2094

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2094 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5F Lot 2105

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2105 - Flagstone City Stage 5F

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager