

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2034

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2034 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2035

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2035 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2036

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2036 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2037

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2037 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2038

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2038 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2039

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2039 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2040

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2040 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2041

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2041 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2042

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2042 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2043

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2043 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2044

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2044 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2045

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2045 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2046

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2046 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2047

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2047 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2048

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2048 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2052

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2052 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2053

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2053 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2054

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2054 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2055

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2055 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2056

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2056 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2057

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2057 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2058

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2058 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2059

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2059 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2060

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2060 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2061

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2061 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2062

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2062 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2063

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2063 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2064

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2064 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2065

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2065 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2066

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2066 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2067

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2067 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2068

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2068 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5G_Lot 2069

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2069 - Flagstone City Stage 5G

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au