

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2172

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2172 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2173

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2173 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2174

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2174 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2175

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2175 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2176

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2176 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2177

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2177 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2178

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2178 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2179

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2179 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2180

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2180 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2181

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2181 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2182

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2182 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2183

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2183 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2336

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2336 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2337

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2337 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2338

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2338 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2339

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2339 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2340

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2340 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2341

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2341 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2342

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2342 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2343

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2343 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5H_Lot 2344

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2344 - Flagstone City Stage 5H

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au