

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2258

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2258 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2258** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2259

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2259 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2259** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2354

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2354 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2354** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2355

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2355 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2355** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2356

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2356 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2356** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2357

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2357 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2357** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2358

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2358 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2358** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2359

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2359 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2359** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2360

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2360 - FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2360** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2411

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2411 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2411** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2412

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2412 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2412** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2413

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2413 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2413** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2414

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2414 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2414** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2415

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2415 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2415** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

6th December 2022 Ref No: Flagstone City Stage 5K_Lot 2416

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 2416 – FLAGSTONE CITY STAGE 5K

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 09/09/2021 and 30/11/2022.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **2416** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No: **1354_SEE Civil_Level 1_Flagstone City Stage 5K.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager