

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2023

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2023 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q_Lot 2024

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2024 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2025

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2025 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2026

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2026 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2027

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2027 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2028

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2028 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2029

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2029 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2030

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2030 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2095

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2095 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2096

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2096 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2097

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2097 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q_Lot 2098

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2098 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2099

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2099 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2100

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2100 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD

jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2101

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2101 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2102

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2102 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD

jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2103

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2103 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2104

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2104 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD

jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2106

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2106 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2107

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2107 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD

jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2108

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2108 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2109

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2109 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2110

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2110 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2111

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2111 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2112

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2112 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2113

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2113 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2149

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2149 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2150

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2150 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD

jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2151

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2151 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2152

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2152 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2153

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2153 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2154

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2154 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650 SEE Civil Level 1 Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306

ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024

Ref No: Flagstone City Stage 5Q Lot 2155

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

CERTIFICATE OF CONTROLLED FILLING LOT 2155 - Flagstone City Stage 5Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 'Residential Slabs & Footings'.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650_SEE Civil_Level 1_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au