

PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2014

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

### CERTIFICATE OF CONTROLLED FILLING LOT 2014 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2015

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

### CERTIFICATE OF CONTROLLED FILLING LOT 2015 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2016

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2016 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2017

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2017 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2018

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2018 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2019

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2019 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2020

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2020 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2021

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2021 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2022

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2022 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2114

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2114 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2115

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2115 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2116

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2116 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2117

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2117 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2118

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2118 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2119

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2119 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2120

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2120 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2121

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2121 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2122

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2122 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2123

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2123 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2124

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2124 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2125

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2125 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2126

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2126 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2127

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

## CERTIFICATE OF CONTROLLED FILLING LOT 2127 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2128

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2128 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2129

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2129 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2130

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2130 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2142

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2142 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2143

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2143 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2144

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2144 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2145

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2145 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2146

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2146 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au



PO Box 1232 PARK RIDGE QLD 4125 ABN: 28 608 830 306 ACN: 608 830 306 Mobile: 0437 776 582 or 0439 776 589 Email: brisbane.south@asct.com.au Web: www.asct.com.au

26/04/2024 Ref No: Flagstone City Stage 5R\_Lot 2148

SEE Civil Pty Ltd 108 Siganto Drive Helensvale QLD 4212

# CERTIFICATE OF CONTROLLED FILLING LOT 2148 - Flagstone City Stage 5R

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 'Guidelines on earthworks for commercial and residential developments'.

Fill was placed on the allotment between 13/09/2023 and 15/04/2024.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on the allotment is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report Ref No:

Ref No: 1650\_SEE Civil\_Level 1\_Flagstone City Stage 5

Please do not hesitate to contact our office if you have any queries.

Yours faithfully

Jason Mckenna Laboratory Manager

ASCT Brisbane South PTY LTD jason.mckenna@asct.com.au