



24th August 2018

Ref No: Flagstone City Stage 1Q_Level 1 Lot Reports

FLAGSTONE CITY STAGE 1Q INDIVIDUAL LEVEL 1 LOT REPORTS

PROJECT: FLAGSTONE CITY STAGE 1Q

CONTRACTOR: SEE CIVIL PTY LTD

INTRODUCTION

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with Clause 8.2 of AS 3798-2007 '*Guidelines on Earthworks for Commercial and Residential Developments*'.

This report includes individual Lot Certification Reports for each allotment where Controlled fill has been placed within Flagstone City Stage 1Q. Any Allotment where no Certification Report has been issued are in Cut and no filling was placed on these Allotments.

Full details of the inspection and testing conducted is included in our report Ref No: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully



Jason Mckenna
Laboratory Manager

ASCT Brisbane South



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 492

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 492 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **492** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 493

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 493 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **493** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 494

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 494 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **494** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 506

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 506 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **506** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 507

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 507 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **507** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 508

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 508 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **508** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 698

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 698 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment 698 is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 699

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 699 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **699** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 700

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 700 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **700** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 701

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 701 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **701** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 702

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 702 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **702** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 703

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 703 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **703** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 704

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 704 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **704** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 705

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 705 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **705** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 706

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 706 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **706** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 707

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 707 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **707** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1Q_Lot 708

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 708 – FLAGSTONE CITY STAGE 1Q

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **708** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au