




24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Level 1 Lot Reports

# FLAGSTONE CITY STAGE 1L

## INDIVIDUAL LEVEL 1 LOT REPORTS



**PROJECT:** FLAGSTONE CITY STAGE 1L

**CONTRACTOR:** SEE CIVIL PTY LTD

## INTRODUCTION

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with Clause 8.2 of AS 3798-2007 '*Guidelines on Earthworks for Commercial and Residential Developments*'.

This report includes individual Lot Certification Reports for each allotment where controlled fill has been placed within Flagstone City Stage 1L. Any Allotment where no Certification Report has been issued are in Cut and no filling was placed on these Allotments.

Full details of the inspection and testing conducted is included in our report Ref No: **345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully



Jason Mckenna  
Laboratory Manager

ASCT Brisbane South



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 540

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 540 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **540** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 541

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 541 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **541** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 542

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 542 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **542** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 543

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 543 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **543** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South

[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 544

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 544 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **544** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 545

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 545 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **545** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 547

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 547 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **547** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South

[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 548

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 548 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **548** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South

[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 549

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 549 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **549** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 550

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 550 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **550** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 551

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 551 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **551** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 552

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 552 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **552** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 688

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 688 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **688** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 689

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 689 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **689** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 690

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 690 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **690** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 691

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 691 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **691** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 692

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 692 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **692** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 693

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 693 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **693** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1L\_Lot 694

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 694 – FLAGSTONE CITY STAGE 1L

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **694** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)