




24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 10\_Level 1 Lot Reports

# FLAGSTONE CITY STAGE 10

## INDIVIDUAL LEVEL 1 LOT REPORTS



**PROJECT:** FLAGSTONE CITY STAGE 10

**CONTRACTOR:** SEE CIVIL PTY LTD

## INTRODUCTION

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with Clause 8.2 of AS 3798-2007 '*Guidelines on Earthworks for Commercial and Residential Developments*'.

This report includes individual Lot Certification Reports for each allotment where controlled fill has been placed within Flagstone City Stage 10. Any Allotment where no Certification Report has been issued are in Cut and no filling was placed on these Allotments.

Full details of the inspection and testing conducted is included in our report Ref No: **345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully



Jason Mckenna  
Laboratory Manager

ASCT Brisbane South



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1O\_Lot 531

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 531 – FLAGSTONE CITY STAGE 1O

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **531** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1O\_Lot 532

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 532 – FLAGSTONE CITY STAGE 1O

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **532** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1O\_Lot 533

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 533 – FLAGSTONE CITY STAGE 1O

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **533** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1O\_Lot 695

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 695 – FLAGSTONE CITY STAGE 1O

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **695** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1O\_Lot 696

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 696 – FLAGSTONE CITY STAGE 1O

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **696** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

[brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web:

[www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

24<sup>th</sup> August 2018

Ref No: Flagstone City Stage 1O\_Lot 697

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 697 – FLAGSTONE CITY STAGE 1O

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **697** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

**345\_SEE Civil\_Flagstone City Stage 1 West Bulk Earthworks\_Level 1**. Revision 1 Dated 20<sup>th</sup> August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)