



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 562

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 562 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **562** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 563

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 563 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **563** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 564

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 564 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **564** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 565

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 565 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **565** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 566

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 566 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **566** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 567

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 567 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **567** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 568

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 568 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **568** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 569

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 569 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **569** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 570

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 570 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **570** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 571

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 571 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **571** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 572

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 572 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **572** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 573

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 573 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **573** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 574

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 574 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **574** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 575

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 575 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **575** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 576

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 576 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **576** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 577

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 577 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **577** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 578

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 578 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **578** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 579

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 579 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **579** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 580

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 580 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **580** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 581

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 581 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **581** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 582

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 582 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **582** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 596

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 596 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **596** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 597

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 597 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **597** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 598

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 598 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **598** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 599

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 599 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **599** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 600

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 600 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **600** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 601

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 601 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **601** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 602

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 602 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **602** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 603

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 603 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **603** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 604

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 604 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **604** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 605

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 605 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **605** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 606

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 606 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **606** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 607

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 607 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **607** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 608

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 608 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **608** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 609

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 609 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **609** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 610

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 610 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **610** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 611

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 611 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **611** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 614

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 614 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **614** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 615

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 615 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **615** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 616

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 616 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **616** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 624

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 624 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **624** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 625

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 625 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **625** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 626

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 626 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **626** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 627

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 627 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **627** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 628

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 628 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **628** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 629

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 629 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **629** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 630

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 630 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **630** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 631

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 631 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **631** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 676

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 676 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **676** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 677

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 677 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **677** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 678

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 678 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **678** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 679

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 679 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **679** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 680

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 680 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **680** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 681

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 681 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **681** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 682

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 682 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **682** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 683

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 683 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **683** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)





## ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 684

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

### LOT 684 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **684** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 685

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 685 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **685** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 686

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 686 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **686** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 687

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 687 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **687** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)



**ASCT Brisbane South**

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: [brisbane.south@asct.com.au](mailto:brisbane.south@asct.com.au)

Web: [www.australiansoilconcretetesting.com.au](http://www.australiansoilconcretetesting.com.au)

3<sup>rd</sup> August 2018

Ref No: Flagstone City Stage 1W\_Lot 90004

SEE Civil Pty Ltd  
108 Siganto Drive  
Helensvale QLD 4210

## **CERTIFICATE OF CONTROLLED LEVEL 1 FILLING**

### **LOT 90004 – FLAGSTONE CITY STAGE 1W**

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **90004** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345\_SEE Civil\_Flagstone Bulk Earthworks West\_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna  
Laboratory Manager

ASCT Brisbane South  
[jason.mckenna@asct.com.au](mailto:jason.mckenna@asct.com.au)