



3rd August 2018

Ref No: Flagstone City Stage 1W_Level 1 Lot Reports

FLAGSTONE CITY STAGE 1W

INDIVIDUAL LEVEL 1 LOT REPORTS



PROJECT: FLAGSTONE CITY STAGE 1W

CONTRACTOR: SEE CIVIL PTY LTD

INTRODUCTION

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with Clause 8.2 of AS 3798-2007 '*Guidelines on Earthworks for Commercial and Residential Developments*'.

This report includes individual Lot Certification Reports for each allotment within Flagstone City Stage 1W.

Full details of the inspection and testing conducted is included in our report Ref No: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully



Jason Mckenna
Laboratory Manager

ASCT Brisbane South



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 562

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 562 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **562** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1**.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 563

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 563 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **563** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 564

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 564 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **564** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 565

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 565 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **565** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 566

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 566 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **566** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 567

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 567 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **567** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 568

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 568 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **568** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 569

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 569 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **569** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 570

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 570 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **570** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 571

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 571 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **571** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 572

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 572 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **572** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 573

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 573 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **573** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 574

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 574 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **574** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 575

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 575 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **575** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 576

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 576 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **576** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 577

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 577 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **577** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 578

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 578 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **578** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 579

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 579 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **579** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 580

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 580 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **580** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 581

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 581 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **581** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 582

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 582 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **582** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 596

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 596 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **596** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 597

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 597 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **597** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 598

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 598 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **598** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 599

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 599 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **599** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 600

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 600 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **600** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 601

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 601 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **601** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 602

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 602 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **602** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 603

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 603 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **603** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 604

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 604 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **604** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 605

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 605 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **605** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 606

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 606 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **606** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 607

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 607 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **607** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 608

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 608 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **608** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 609

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 609 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **609** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 610

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 610 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **610** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 611

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 611 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **611** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 614

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 614 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **614** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 615

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 615 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **615** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 616

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 616 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **616** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 624

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 624 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **624** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 625

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 625 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **625** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 626

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 626 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **626** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 627

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 627 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **627** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 628

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 628 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **628** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 629

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 629 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **629** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 630

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 630 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **630** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 631

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 631 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **631** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 676

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 676 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **676** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 677

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 677 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **677** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 678

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 678 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **678** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 679

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 679 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **679** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 680

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 680 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **680** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 681

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 681 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **681** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 682

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 682 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **682** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 683

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 683 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **683** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 684

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 684 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **684** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 685

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 685 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **685** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 686

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 686 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **686** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 687

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 687 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **687** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

3rd August 2018

Ref No: Flagstone City Stage 1W_Lot 90004

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 90004 – FLAGSTONE CITY STAGE 1W

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 *'Guidelines on earthworks for commercial and residential developments'*.

Fill was placed on the allotment between 9/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **90004** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 *'Residential Slabs & Footings'*.

Full details of the inspection and testing conducted is included in our report ref no: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au