




24th August 2018

Ref No: Flagstone City Stage 1M_Level 1 Lot Reports

FLAGSTONE CITY STAGE 1M

INDIVIDUAL LEVEL 1 LOT REPORTS



PROJECT: FLAGSTONE CITY STAGE 1M

CONTRACTOR: SEE CIVIL PTY LTD

INTRODUCTION

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with Clause 8.2 of AS 3798-2007 '*Guidelines on Earthworks for Commercial and Residential Developments*'.

This report includes individual Lot Certification Reports for each allotment where Controlled fill has been placed within Flagstone City Stage 1M. Any Allotment where no Certification Report has been issued are in Cut and no filling was placed on these Allotments.

Full details of the inspection and testing conducted is included in our report Ref No: **345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1.**

Please do not hesitate to contact me if you have any queries.

Yours faithfully



Jason Mckenna
Laboratory Manager

ASCT Brisbane South



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 330

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 330 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **330** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 331

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 331 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **331** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 389

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 389 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **389** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 390

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 390 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **390** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 391

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 391 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **391** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 392

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 392 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **392** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 393

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 393 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **393** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN: 608 830 306

ABN: 73 193 500 470

Mobile: 0437 776 582 or 0439 776 589

Email: brisbane.south@asct.com.au

Web: www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 395

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 395 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **395** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 396

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 396 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **396** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au



ASCT Brisbane South

PO Box 1232

Park Ridge, QLD 4125

ACN:

608 830 306

ABN:

73 193 500 470

Mobile:

0437 776 582 or 0439 776 589

Email:

brisbane.south@asct.com.au

Web:

www.australiansoilconcretetesting.com.au

24th August 2018

Ref No: Flagstone City Stage 1M_Lot 397

SEE Civil Pty Ltd
108 Siganto Drive
Helensvale QLD 4210

CERTIFICATE OF CONTROLLED LEVEL 1 FILLING

LOT 397 – FLAGSTONE CITY STAGE 1M

Australian Soil and Concrete Testing was commissioned by SEE Civil Pty Ltd to provide earthworks inspection and testing services on a 'Level 1' basis in accordance with the requirements of AS 3798-2007 '*Guidelines on earthworks for commercial and residential developments*'.

Fill was placed on the allotment between 09/02/18 and 30/07/18.

Based on the observations made by Australian Soil and Concrete Testing and the test results obtained during construction the structural fill placed on allotment **397** is considered to have been carried out in general accordance with AS3798-2007 and is considered to be Controlled Fill as defined in AS2870 – 2011 '*Residential Slabs & Footings*'.

Full details of the inspection and testing conducted is included in our report ref no:

345_SEE Civil_Flagstone City Stage 1 West Bulk Earthworks_Level 1. Revision 1 Dated 20th August 2018.

Please do not hesitate to contact me if you have any queries.

Yours faithfully

Jason Mckenna
Laboratory Manager

ASCT Brisbane South
jason.mckenna@asct.com.au